



# Encoder Top, Component Side



To accessories connector on transmitter. Please see the details drawing.

Encoder, solder side

J2



**Encoder J2 connector pin assignments**

Each of these connectors are cut from parts list item 37. You will need 10 three pin connectors and 16 two pin connectors.

J3, to display

# Encoder Bottom, Solder Side

